Sliptest Australia Pty Ltd
NATA Accreditation No: 15374
11 Fuchsia Way Gaven QLD 4211, Gaven, QLD, 4211
kathryn@sliptest.com.au
www.sliptest.com.au
1300 754 783

NATA Accreditation No.15374 for Compliance with ISO 17025 – Testing

Aerotek Australia Pty Ltd - Treadrite Clear #57727 - 4L 57729-4L 57790-1L 57820-10L 11-02-2025 - Wet Sliptest MO140225-12 14 Feb 2025

Slip Resistance Classification of New Pedestrian Surfaces - AS4586:2013

This Test Report Is In Accordance with Appendix A	Wet Pendulum Test
Date Tested:	14 Feb 2025
Test Report Number:	MO140225-12
Client Name & Billing Address:	Aerotek Australia Pty Ltd - PO BOX 1556, Toowong, QLD 4066
Surface Tested :	Treadrite Clear #57727 - 4L 57729-4L 57790-1L 57820-10L 11/02/2025
Wet Pendulum Test carried out using :	Slider 55 (TRL) Rubber slider
Temp Correction for Type 55 (TRL) Slider	24-26 = +1
Any Variations to Standards	Variation of Standards only 1 Sample Available for testing
Testing Officer / Approved Signatory:	Mitchell Ording
Pendulum in use - Calibration Date :	#1109 - Munro-Stanley Portable Skid Tester (C: 27.04.23 - BS 7976-3:2002+A1:2013)
Signature of Approved Signatory :	

Test Results : (Samples and Test Information Supplied by Client)

Sample No.	Swing 1	Swing 2	Swing 3	Swing 4	Swing 5	Mean BPN	SCV :	Surface Picture
Area 1	70	70	69	69	68	69	N/A	
Area 2	72	72	69	69	69	69	N/A	
Area 3	70	70	70	70	70	70	N/A	
Area 4	72	72	69	69	69	69	N/A	

Submitted by: Mitchell Ording @ 10:09:56 14 Feb 2025
Submission ID: 19760847
Environment friendly, paperless solution by www.formitize.com

Issue: Controlled Document ID: 23422 - 1 PAGE TEST FORM (AS4586 ONLY - Wet or Dry Pendulum Testing) Version: 186

Sample No.	Swing 1	Swing 2	Swing 3	Swing 4	Swing 5	Mean BPN	SCV :	Surface Picture
Area 5	73	73	72	72	71	72	N/A	 

Reported SRV For Test Area :	70
Variation to Standard Mean BPN Slip Resistance Value (SRV)	70
Corrected Mean BPN (SRV) Slider 55 ONLY	71
CLASSIFICATION using Slider 55 (TRL Slider)	P5 = >44

Declaration: The factual matters stated within this report are, to the best of my knowledge, true and correct. I have completed all enquiries that I consider appropriate in formulating my conclusions. The opinions stated by me within this report are genuinely held by me. The report contains reference to all matter which I regard as significant. I understand that my overriding duty as an expert is to assist the Court and have complied with this duty. The information presented herein and on the Sliptest Report is copyright and is protected by copyright law, any reproduction of this information and test report except in full is prohibited. Any enquiries in relation to this report should be directed to Sliptest Australia Pty. Ltd.quoting the applicable test report number. Accredited for Compliance with ISO/IEC 17025. Sliptest Australia Pty. Ltd. performed this on site test with reference to the following Australian Standard testing criteria, of AS 4586:2013 Classification of new pedestrian surface materials & AS 4663:2013 Classification of existing pedestrian surface materials - Appendix A - Wet Pendulum Test Method and Hand Book HB 198: 2014. This report and covering documentation was prepared by SliptestAustralia Pty. Ltd. on behalf of our client as named in the report. Neither Sliptest Australia Pty. Ltd. nor any person acting on our behalf (a) makes any warranty, express or implied, with respect to the use of any information or methods disclosed in this report or (b) assumes any liability with respect to the use of any information or methods disclosed in this report or covering information. Any recipient of this document, by their acceptance or use of this document, releases Sliptest Australia Pty. Ltd. and their affiliates from any liability for direct, indirect, consequential or special loss or damage whether arising in contract, warranty, express or implied, tort or otherwise, and irrespective of fault, negligence and strict liability.

Page 1 of 1 - END OF REPORT